

# Safety Recall

## Generation 2 and ChildESIGNS Drop Side Crib



### Suffocation and Strangulation Hazard

The crib's plastic hardware can break which can cause the drop side of the crib to detach from a corner of the crib or the crib's mattress support to detach from the crib frame. When either detaches, it creates a space into which an infant or toddler can roll and become wedged or entrapped, creating a risk of suffocation or strangulation.

Customers should stop using this product immediately and find an alternative, safe sleeping environment for their baby.

Do not attempt to fix these cribs. Customers may return the crib to the place of purchase to receive an in-store credit.

For additional information, visit [www.cpsc.gov](http://www.cpsc.gov)  
or call **800-638-2772**.