

Safety Recall

Step2 Push Around Buggy and Whisper Ride Buggy

Model: 715700, 792300, 7923TA, 7923OR, 796600, 7966TA, 768400, 882900, 885700; **UPC:** 733538715701, 733538768493, 733538792306, 733538792313, 733538796694, 733538882991, 733538885794



Sold from 1999 through March 2010

Affected buggies have pins with yellow plastic knobs on the back of the buggy. The pin can become loose and allow the handle to separate from the buggy. Buggies with handles attached with a bolt and nut are NOT affected.

Please inspect the buggy. If the buggy has a pin with a yellow plastic knob, **immediately stop using the buggy and contact Step2 for a repair kit.**

Call Step2 toll free at **1-866-860-1887** or visit www.step2.com to receive a free repair kit.

SAFETY RECALL

Step2 is recalling the **Push Around Buggy and Whisper Ride Buggy** with yellow plastic knob pins. The yellow pin can become loose and allow the handle to separate from the buggy.

Buggies that have a handle attached by a bolt and nut are NOT included in this recall.

Consumers should immediately stop using the recalled buggy and contact Step2 for a free repair kit at **866-860-1887** or **www.step2.com**.

6/13/10

SAFETY RECALL

Step2 is recalling the **Push Around Buggy and Whisper Ride Buggy** with yellow plastic knob pins. The yellow pin can become loose and allow the handle to separate from the buggy.

Buggies that have a handle attached by a bolt and nut are NOT included in this recall.

Consumers should immediately stop using the recalled buggy and contact Step2 for a free repair kit at **866-860-1887** or **www.step2.com**.

6/13/10